



The Waukesha 7042 and 7044 have sufficient lube capacity to allow use of a single Model 600-8 HD centrifuge for bypass oil cleaning. Remove any existing bypass filters before centrifuge installation.


Supply oil from the oil pump outlet elbow or any point after, but upstream other components..

Return oil into pan, a port tapped into a crankcase access cover or into front geartrain

# WAUKESHA 7042



Supply Point at or after Oil Pump



To the best of our knowledge, this information is accurate and will provide safe and efficient operation of both the Spinner II centrifuge and the engine. Engines and options are subject to change. If you experience any problems with installation or operation, please contact your Spinner II Distributor or call our customer service department, at the following phone number: 800-231-7746 (713-682-3651 in TX).

## INSTALLATION BULLETIN

### SPINNER II

©Spinner II Products / T. F. Hudgins, Incorporated  
Houston, Texas 77292-0946

2	Add 7044 to title & 2nd return port, Del. 8gpm	19 JAN 01	MP
1	Replace 2x200HD with 600HD	19 Feb 98	sr
REV	CHANGE	DATE	BY

## Installation of Spinner II Centrifuge on Waukesha 7042 & 7044

DRAWN	CHECKED	APPD	PROJECT	DATE	DWG
sr				21 Feb 1994	<b>A1-4983-2</b>